



A-A



Nicht für Fliehkraftkupplung geeignet
not suitable for centrifugal clutch

Diese Riemenscheibe funktioniert nur mit der
 P343-31-11 Wellenadapter, Eingangswelle
 This pulley works only with the
 P343-31-11 Shaft adapter, input shaft



P343-3x-xx Übersicht	
Bauteilnr.	ØA
P343-31-12	80
P343-31-13	85
P343-31-14	90
P343-31-15	95
P343-31-16	100
P343-31-17	105
P343-31-18	110
P343-31-19	115
P343-31-20	120
P343-31-21	125
P343-31-22	130
P343-31-23	135